



# Trumbull Manufacturing

3850 Hendricks Road, Youngstown, Ohio 44515

Phone: 330.270.7888 | Toll Free: 877.504.1507 | Fax: 330.392.0756

[www.trumbull-mfg.com](http://www.trumbull-mfg.com)

## COUNTERBORES FOR THROUGH-THE-LID ANTENNA MOUNTING










Drilling holes in existing cast iron lids may save money in the short run. However, most iron lids do not have the thickness for a counterbore. If lids are simply drilled without a counterbore, the result is a trip hazard. Drilling iron lids in the field frequently results in cracks in the lid.

### Solution:

Our lids feature a molded **COUNTERBORE** allowing recessed installation of antenna to eliminate trip hazard or damage.



### Current Counterbore Options



*i* As some meter manufacturers offer more than one through-the-lid antenna or adapter, dimensions should be confirmed at time of order.

For dimensions, load ratings and additional options, refer to product information chart on pages 18 - 28.